



MERCURY-MERCRUISER





MOTORI HP 40 EFI-50-75 4 TEMPI

code		original code	A	F	H	H ₁	
ME001	FM-1	31640Q4	90	7/16"W	65	17	ZN
ME001AL	FM-1/AL	31640Q4	90	7/16"W	65	17	AL
ME001MG	FM-1/MG	31640Q4	90	7/16"W	65	17	MG




MOTORI HP 80-140

code		original code	A	F	H	H ₁	
ME002	FM-2	34127A1	90	7/16"W	100	18	ZN
ME002AL	FM-2/AL	34127A1	90	7/16"W	100	18	AL



MOTORI HP 20

code		original code	A	C	F	H	
ME003	FM-3	47820A1	97	74	5/16"W	30	ZN



MOTORI HP 20-25

code		original code	A	C	H	H ₁	
ME004	FM-4	94286T1	116	94	51	14	ZN